



**SBLM Architects**

11430 N. Kendall Drive, Suite 310  
 Miami, FL 33176  
 Telephone 305 412 9187  
 Fax 305 412 6731  
 dfranco@sblm.com  
 www.sblm.com

**Addendum #2**

Issue Date	Issue to
March 11, 2010	Petco
Project Name	SBLM Project Number
Petco Cary, NC	09147
Site Address	Project Location
213 Crossroads Boulevard	Cary, NC
City, State, Zip	File Code
Cary, NC 27518	
Distribution	
Clay Earley	Petco
Jon Arnold	Collins and Arnold Construction
Darren Frost	R.D. Michaels, Inc.
Phil Gerardi	Gerardi Construction
Bryan Marolf	Marolf Construction

This Revision shall hereby be and become part of the Contract Documents, the same as if originally bound thereto.

The following clarifications, amendments, additions, revisions, changes, and/or modifications change the original Contract Documents only in the manner and to the extent hereinafter specified in this Bulletin.

This Revision consists of the following documents:

Drawing Number	Item No.	Description
A0.1	2.01	Revised drawing issue log.
A2.1	2.02	Added detail tag 17/A8.2 around electrical panel and phone board.
	2.03	Added dimensions at pre-sales walls.
	2.04	Changed PTD Area B to PTD Area A at back of house wall.
	2.05	Revised dimension for PTD Area A at rear wall.
	2.06	Revised wall type at front of store to P1 instead of P1A.
A2.2	2.07	Added hallway #2 tag and floor finish for hallway exiting side door.
A2.4	2.08	Added note for Gyp. Bd. Soffit at hallway #2
	2.09	Added diffuser locations to plan.
	2.10	Added track light by office area.
A2.5	2.11	Revised location of RTU #1 to match structural.
A3.1	2.12	Added hallway #2 to finish schedule.
A4.1	2.13	Added notes for existing roof screening to clarify new from existing.
	2.14	Added detail number to railing note.

Drawing Number	Item No.	Description
A4.1	2.15	Revised graphic for brick to differentiate existing and new brick finish.
A5.2	2.16	Added note to detail 4.
A5.3	2.17	Added notes to refer to structural drawings for lintel details and ramp details.
A5.4	2.18	Added note for new brick and existing brick.
	2.19	Added storefront height.
A6.1	2.20	Added note to details 6,7, and 8 to refer to structural drawings.
A7.1	2.21	On detail 1 added detail tag 13.
	2.22	Added note for tile wainscot between storefront in grooming salon.
	2.23	On detail 5 corner guard note was missing.
	2.24	Added room tags for hallway #1 and #2.
	2.25	Dimension for hallway #2 added.
A7.1A	2.26	Added detail number for railing on large scale plan #1.
A8.2	2.27	Added details #14 for bollard detail and #17 for floor striping at pre-sales.
A9.1	2.28	Revised break room elevation #2.
A9.2	2.29	Relocated detail tag 03 on elevation 1 of grooming salon and added tile start point.
S3.0	2.30	Added missing exhaust fan to roof plan.
E1.1	2.31	Added track lighting to lighting fixture schedule.
	2.32	Added track lighting mounting height.
E1.2	2.33	Added circuit for track lighting per revised RCP.
E2.1	2.34	Added track lighting to lighting plan per revised RCP.
E2.1A	2.35	Added dimensions to track lighting.

End of Addendum #2

Prepared by SBLM Architect's.